UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 7,399,041 B2

DATED : July 15, 2008

INVENTOR(S): Prentner, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover page in the abstract (57), "pawl component the entraining rocker" should read -- pawl component, the entraining rocker--

Column 2, line 13, "BRIEF SUMMARY OR THE INVENTION" should read -- BRIEF SUMMARY OF THE INVENTION --

Column 4, line 18, "between the guide rail 12 end the" should read -- between the guide rail 12 and the --

Column 8, line 33, "the pawl component in a refraction direction on entering the" should read -- the pawl component in a refraction direction on entering the --

MAILING ADDRESS OF SENDER: Norris McLaughlin & Marcus, PA 875 Third Avenue, 18th Floor New York, NY 10022

PATENT NO. US 7,399,041 B2

No. of additional copies 0



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.